

# Office of The Chief Medical Officer, Ghaziabad

Ref.No. DSO/IDSP/2023/2367

Dated:- 21-10-2023

## WATER TEST REPORT

ADDRESS:- DELHI PUBLIC SCHOOL, (SENIOR WING) SITE-03, MEERUT ROAD, GHAZIABAD.

PREVIOUS SAMPLE COLLECTION DATE	SAMPLE COLLECTION AREA	SAMPLE WATER WAS BEING USED	SAMPLE ID	RESULT
N/A	N/A	N/A	N/A	N/A

No of sample collected : 01

SAMPLE COLLECTION DATE	SAMPLE COLLECTION AREA	SAMPLE WATER WAS BEING USED	SAMPLE ID	RESULT
12-10-2023	RO WATER	DRINKING	1402	Satisfactory

### Test Result

H<sub>2</sub>S Water test kit : Negative (-Ve) after 24-48 hrs incubation

### Comments:-

H<sub>2</sub>S water test kit report - ve reflects that water is free from Coliforms Organism.

### Recommendation:

Given water safe for drinking purpose.

Lab Technician  
IDSP Lab  
Ghaziabad

(Dr. Suruchi Saini)  
Microbiologist IDSP Lab  
Ghaziabad

(Dr R.K Gupta)  
District Surveillance Officer  
Ghaziabad  
District Surveillance Officer  
District Public Health Expert  
District Ghaziabad

# Office of The Chief Medical Officer, Ghaziabad

Ref.No: DSO/IDSP/2023/2368

Date:- 21-10-2023

## Health & Hygiene Certificate

It is certified that a combined inspection team headed by Mr. Sujeet Kumar Rai from IDSP UNIT, Ghaziabad inspected the premises DELHI PUBLIC SCHOOL, (SENIOR WING) SITE-03, MEERUT ROAD, GHAZIABAD on 12-10-2023 and found DELHI PUBLIC SCHOOL, (SENIOR WING) SITE-03, MEERUT ROAD, GHAZIABAD has safe water facilities for the person is maintaining hygienic sanitation conditions in the School or Organization. This certificate is issued with the condition that the water quality will be maintained in future otherwise, it will automatically stand cancelled on proof.

Based on Ref: DSO/IDSP/2023/2367

(Dr. R K Gupta)

**District Public Health Expert  
Ghaziabad**

District Surveillance Officer  
District Public Health Expert  
District Ghaziabad

To

DELHI PUBLIC SCHOOL,  
(SENIOR WING) SITE-03, MEERUT ROAD,  
GHAZIABAD.

# Office of The Chief Medical Officer, Ghaziabad

Ref.No. DSO/IDSP/2023/2969

Dated:- 21-10-2023

## WATER TEST REPORT

ADDRESS:- DELHI PUBLIC SCHOOL, (JUNIOR WING) SITE-03, MEERUT ROAD, GHAZIABAD.

PREVIOUS SAMPLE COLLECTION DATE	SAMPLE COLLECTION AREA	SAMPLE WATER WAS BEING USED	SAMPLE ID	RESULT
N/A	N/A	N/A	N/A	N/A

No of sample collected : 01

SAMPLE COLLECTION DATE	SAMPLE COLLECTION AREA	SAMPLE WATER WAS BEING USED	SAMPLE ID	RESULT
12-10-2023	RO WATER	DRINKING	1403	Satisfactory

### Test Result

H<sub>2</sub>S Water test kit : Negative (-Ve) after 24-48 hrs incubation

### Comments:-

H<sub>2</sub>S water test kit report - ve reflects that water is free from Coliforms Organism.

### Recommendation:

Given water safe for drinking purpose.

Lab Technician  
IDSP Lab  
Ghaziabad

(Dr. Suruchi Saini)  
Microbiologist IDSP Lab  
Ghaziabad

(Dr R.K Gupta)  
District Surveillance Officer  
Ghaziabad  
District Surveillance Officer  
District Public Health Expert  
District Ghaziabad

# **Office of The Chief Medical Officer, Ghaziabad**

Ref.No: DSO/IDSP/2023/2370

Date:- 21-10-2023

## **Health & Hygiene Certificate**

It is certified that a combined inspection team headed by Mr. Sujeet Kumar Rai from IDSP UNIT, Ghaziabad inspected the premises DELHI PUBLIC SCHOOL, (JUNIOR WING) SITE-03, MEERUT ROAD, GHAZIABAD on 12-10-2023 and found DELHI PUBLIC SCHOOL, (JUNIOR WING) SITE-03, MEERUT ROAD, GHAZIABAD has safe water facilities for the person is maintaining hygienic sanitation conditions in the School or Organization. This certificate is issued with the condition that the water quality will be maintained in future otherwise, it will automatically stand cancelled on proof.

Based on Ref: DSO/IDSP/2023/2369



(Dr. R K Gupta)  
District Public Health Expert  
Ghaziabad  
District Surveillance Officer  
District Public Health Expert  
District Ghaziabad

To

DELHI PUBLIC SCHOOL,  
(JUNIOR WING) SITE-03, MEERUT ROAD,  
GHAZIABAD.